U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECT	ION I
MANUFACTURER'S NAME Aztec Chemical, Inc.	EMERGENCY TELEPHONE NO. (213) 448-9262
ADDRESS (Number, Street, City, State, and ZIP Code) 212 S. Tu CHEMICAL NAME AND SYNONYMS	rner Aye., West Covina. Ca. 91791
acrylic lacquer	AZ 576 NFA
CHEMICAL FAMILY	DPM 5404-9591 Anthracite

SECTION II - HAZARDOUS INGREDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	%	(Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Unite)
PIGMENTS contains no lead	8	50	BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES			%	TLV (Units	
chlorinated hydrocarbon mixture		70	100		
(methylene chloride, perchloroethylene, trichloroethylene)					
					_

SECTION III - PHYSICAL DATA				
BOILING POINT (°F.)	105	SPECIFIC GRAVITY (H20=1)	1, 2	
VAPOR PRESSURE (mm Hg.)	150	PERCENT, VOLATILE BY VOLUME (%)	70	
VAPOR DENSITY (AIR=1)	3	EVAPORATION RATE (MEK=1)	2	
SOLUBILITY IN WATER	not sol	uble		
APPEARANCE AND ODOR pigme	ented liquid, s	sweet odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA							
FLASH POINT (Method used)	none T.C.C.	FLAMMABLE LIMITS none	Lal	Uel			
compatible with dry, foam or C0 SPECIAL FIRE FIGHTING PROCEDURES 2							
SPECIAL FIRE FIGHTING PROCEDI	- · · - •	ained aspirators					
UNUSUAL FIRE AND EXPLOSION I	HAZARDS none						
;							

SECTION V - HEALTH HAZARD DATA				
THRESHOLD LIMIT VALUE 100 p. p. m. calculated				
EFFECTS OF OVEREXPOSURE burn eyes and irritate, defat the skin. Is toxic if swallowed.				
EMERGENCY AND FIRST AID PROCEDURES				
Wash skin and eyes with large amounts of water. Breathe fresh air if dizzy				
or respirate. If swallowed, give warm salt water and repeat until vomit is				
clear. Lie down and cover eyes. Immediately call a physician.				

	e e e e e e e e e e e e e e e e e e e	SECTI	ION VI - REACTIVITY DATA
STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	x.	
INCOMPATABILITY	Materials to avoid	ox	xidizers
HAZARDOUS DECO	MPOSITION PROD	octs; to:	oxic fumes (jet eg)
HAZARDOUS MAY OC		UR	CONDITIONS TO AVOID
POLYMERIZATION	WILL NOT	OCCUR	x

SECTION VII - SPILL OR LEAK PROCEDURES				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED				
soak and scoop up with an inert filler. Dispose as hazardous paint waste				
waste disposed with approved incineration or permitted land fill				

And the second s	SECTION VIII - SPECI	AL PROTECTION I	INFORMATION
RESPIRATORY PI	ROTECTION (Specify type) car	tridge filter	
VENTILATION	LOCAL EXHAUST		SPECIAL
MECHANICAL (General)			OTHER CONTROL CONTROL
PROTECTIVE GLO	OVES X	EYE PROTECTI	State of the state
OTHER PROTECT	ive equipment elective		

SECTION	IX - SPECIAL PRECAUTIONS	and the second section of the section of t	
PRECAUTIONS TO ME TAKEN IN HANDLING AND			
store in ambient dry conditions.	Keep containers tightly sealed.		
OTHER PRECAUTIONS			
none			

GPO 934-110

Form OSHA-20 Rev. May 72